

Recall/Special Service Campaign



Date of Campaign : 27/01/2021
Campaign Type : Recall/Special Service Campaign
Product Description : Hilux & Fortuner

Production Year	Brand	Vehicle Model	Affected Vehicle Range *	No. of Affected Vehicles
2018 to 2019	TOYOTA	Hilux & Fortuner	MR0DB9CDXK5140188 to MR0HA8CD6K1058075	1784

* Not all vehicles in these VIN ranges affected.

Description:

In the brake booster of the subject vehicles, due to improper molding condition of the resin piston, the strength of piston could degrade. If this were to occur, the piston may break by operating the brake pedal repeatedly, and in the worst case, loss of braking assist while driving could increase the vehicle stopping distance.

Procedure:

As per "Technical instruction" advised by TMC.

For More Information:

Customers driving these vehicles may please contact M/s. Saud Bahwan Automotive LLC for further details / booking appointment etc. from 27/01/2021.

Contact Details:

Toll free No. 80073000 on all working days between 08:30 to 17:30 hrs. after 27/01/2021.