

## Recall/Special Service Campaign



Date of Campaign : 05/04/2023  
Campaign Type : Recall/Special Service Campaign  
Product Description : Welding to the joint of the Fender Apron

Production Period	Brand	Vehicle Model	Affected VIN Range	No. of Affected Vehicles
17 Nov ,2020 to 12 Oct ,2021	TOYOTA	RAIZE	MHKA1BA0NJ014078 to MHKAB1BA5NJ001985	8

**Note: Not all vehicles in these VIN ranges, are affected and/or sold in your country.**

### Description:

We have been reported from Daihatsu that in the fender apron of the subject vehicles (which are OEM from Daihatsu), due to improper welding control in the welding process, there is a possibility that the joining portion may not have a sufficient strength. If the vehicle rides over a step, such as an indented road surface, during highway driving conditions, the welded portion could separate, and in the worst case, the vehicle control could be loss.

### Procedure:

As per "Technical instruction" advised by TMC.

### For More Information:

Customers driving these vehicles may please contact M/s. Saud Bahwan Automotive LLC for further details / booking appointment etc from 05/04/2023.

### Contact Details:

Toll free No. 80073000 on all working days between 08:30 to 17:30 hrs after 05/04/2023.