



تاريخ بدء الاستدعاء : ٢٠١٧/٠٩/١٣

نوع الاستدعاء : السلامة والأمان

وصف المنتج : تويوتا (ألفرد ، ياريس) لكزس (ES, IS, LFA)

السنة	العلامة	طراز المركبة	رقم تعريف شاصي السيارات المتأثرة	عدد السيارات المتأثرة
٢٠١٢- ٢٠١٠	تويوتا	ألفرد	JTNGE26H088140655 JTNGK26HXD8067984	٧٤١
٢٠١٢- ٢٠٠٥	تويوتا	ياريس صالون	JTDBT923OCL029948 JTDBW923XDL065462	١,٢٢٥
٢٠١٢- ٢٠١٠	لكزس	LFA	JTHHX88H1B1000049 JTHHX88H9B1000039	٥
٢٠١٢- ٢٠٠٩	لكزس	IS250 / 350	JTHBG2620C5002782 JTHFG2525D2502989	١٠٩
٢٠١٢- ٢٠٠٩	لكزس	ES350	JTHBJ46G0C2488827 JTHBJ46GX2509912	١٠٢

الخلل :

قد يؤدي تحلل المادة الدافعة إلى تمزق ناخب هواء الوسادة الهوائية وذلك نتيجة التعرض لظروف خارجية ضارة لمدة طويلة ، مما قد يؤدي إلى إصابة أو وفاة ركاب السيارة .

الإجراء :

استبدال مجمع الوسادة الهوائية للراكب الأمامي وفقاً لتعليمات تويوتا موتور كوربوريشن.

لمزيد من التفاصيل :

يرجى من قائدي السيارات المذكورة الاتصال بشركة سمود بهوان للسيارات ش.م.م لمعرفة المزيد من التفاصيل وأخذ موعد وذلك اعتباراً من ٢٠١٧/٠٩/١٣ فصاعداً.

معلومات الاتصال :

يرجى الاتصال على رقم الهاتف المجاني ٨٠٠٧٣٠٠٠ خلال أيام الدوام الرسمي من الساعة ٨:٣٠ صباحاً إلى الساعة ٥:٣٠ عصرًا بعد تاريخ ٢٠١٧/٠٩/١٣.



Sultanate of Oman
The Public Authority For Consumer Protection

OMAN DAILY OBSERVER [ENGLISH], Dt: 13.09.2017



SAUD BAHWAN Group

Recall Campaign



Date of Recall : 13/09/2017
Recall Type : Safety & Security
Product Description : Toyota (Alphard, Yaris) & Lexus (LFA, IS, ES)

Production Year	Brand	Vehicle Model	Affected Vehicle Range	No. of affected Vehicles
2010-2012	Toyota	Alphard	JTNGE26H088140655 to JTNGK26HDXD8067984	741
2005-2012	Toyota	Yaris (Sedan)	JTDBT9230CL029948 to JTDBW923XDL065462	1,225
2010-2012	Lexus	LFA	JTHHX8BH1B1000049 to JTHHX8BH9B1000039	05
2009-2012	Lexus	IS250 / 350	JTHBG2620C5002782 to JTHFG2525D2502989	109
2009-2012	Lexus	ES350	JTHBJ46G0C2488827 to JTHBJ46GXC2509912	102

Description:

Propellant degradation after prolonged exposure to adverse ambient conditions may result in airbag inflator rupture causing injury and even death to vehicle occupants.

Procedure:

To replace the front passenger airbag inflator assy as advised in TMC technical instructions.

For more information:

Customers driving these vehicles may please contact M/s. Saud Bahwan Automotive LLC for further details / booking appointment etc. from 13/09/2017 onwards.

Contact Details:

Toll free No. 80073000 on all working days between 08:30 to 17:30 hrs after 13/09/2017