

Recall Campaign



Date of Recall : 17/08/2015
 Recall Type : Safety
 Product Description : COROLLA/RAV4/LEXUS SC430
 Recall Unit : Airbag

| Production Period | Brand | Vehicle Model | Affected Vehical Range | No.of Affected Vehicles |
|-------------------|--------|---------------|--|-------------------------|
| 2000 To 2003 | TOYOTA | COROLLA | JTDBR22E110011853 TO JTDBR22E833074157 | 1895 |
| 2001 To 2002 | LEXUS | SC430 | JTHFN48Y530020230 TO JTHFN48Y130034612 | 30 |
| 2003 To 2007 | TOYOTA | COROLLA | JTDBR22E330129129 TO JTDBR22E973215162 | 11737 |
| 2003 To 2005 | TOYOTA | RAV4 | JTEHH20V640263503 TO JTEHH20V855021722 | 1216 |

Description:

The inflator, due to moisture intrusion, may increase the risk of injury during deployment.

Procedure:

Replace airbag inflator.

For More Information:

Customers driving these vehicles may please contact M/s. Saud Bahwan Automotive LLC for further details / booking appointment etc. from 17.08.2015

Contact Details:

Toll free No. 80073000 on all working days between 08:30 to 17:30 hrs. after 17.08.2015