

Recall/Special Service Campaign



Date of Campaign : 05/04/2023
 Campaign Type : Recall/Special Service Campaign
 Product Description : Fr Seat back frame modification

Production Period	Brand	Vehicle Model	Affected VIN Range	No. of Affected Vehicles
6 Dec, 2019 through 17 Jun, 2021	TOYOTA	HIGHLANDER	5TDLB3CH0LS000186 to 5TDLB3CHXMS050577	267

Note: Not all vehicles in these VIN ranges, are affected and/or sold in your country.

Description:

The subject vehicles are equipped with front seats which are constructed with a certain seat-back frame. Due to wearing of the forming dies and insufficient inspection instructions, certain specific points on the seat-back frames were not manufactured with the minimum radius criteria. In this condition, these seat-back frames do not comply with ECE UNR17 and certain regulation.

Procedure:

As per "Technical instruction" advised by TMC.

For More Information:

Customers driving these vehicles may please contact M/s. Saud Bahwan Automotive LLC for further details / booking appointment etc from 05/04/2023.

Contact Details:

Toll free No. 80073000 on all working days between 08:30 to 17:30 hrs after 05/04/2023