



Recall/Special Service Campaign



Date of Campaign : 17/02/2021
 Campaign Type : Recall Campaign
 Product Description : Hiace

Production Year	Brand	Vehicle Model	Affected Vehicle Range*	Nos. of Affected Vehicles
November 30, 2017 through November 11, 2020	TOYOTA	HIACE	JTGSS22PXJ0172436 to JTFHS02PXM0108758	597

* Not all vehicles in these VIN ranges affected.

Description:

The subject vehicles are equipped with a VSC (Vehicle Stability Control) system (Including TRC-Traction Control). Due to incorrect programming of the Engine ECU, there is a possibility that the VSC or TRC system will not work correctly. In this condition, these vehicles may not comply with the general requirements of GSO42.

Procedure:

Reprogram the Engine ECU.

For More Information:

Customers driving these vehicles may please contact M/s. Saud Bahwan Automotive LLC for further details / booking appointment etc, from 17/02/2021.

Contact Details:

Toll free No. 80073000 on all working days between 08:30 to 17:30 hrs. from 17/02/2021.